

CATALOG

Cars and Commercial Vehicles



DESCRIPTION Passenger cars and vans from various bankruptcies, seizures and breaches of contract.

START 13 october 2020 to 10:00

END DATE 20 october 2020 from 18:00

VIEWING

- Wednesday October 14 2020 from 15:00 until 17:00
BE - 2630 Aartselaar, Helststraat 47

AUCTIM PARTNER **MOYERSOEN NV**
Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452.153.622

DELIVERY

- Wednesday October 28 2020 from 09:00 until 12:00
BE - 2630 Aartselaar, Helststraat 47

Online bidding only!

Catalog created on 20 october 2020 to 06:01

	Lot	Description	Start price
	1	<p>FORD Fiesta</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 155880 km. 1st registration: 06/10/2008 Colour: Grey Engine capacity: 1399 cc. Engine power: 50 Kw. Emission class: Euro 4 CO² emissions: 119 g / km. Chassis number: WF0HXXGAJH8C40364 Number of keys: 2</p> <p>Option (s): air conditioning, electric windows, fog lights, radio / CD. Attention: battery remote control empty</p> <p>Visible damage: front bumper, front left bumper, front right bumper, rear left bumper and general usage traces. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p> <p>Carpass, Maintenance booklet, Inspection certificate, valid until: 01/09/2020</p>	500 €
	22	<p>PONTIAC 6000 2G19X</p> <p>Category: Passenger car. Fuel gasoline Transmission: Automatic Mileage reading: 156873 km. 1st registration: 31/05/1988 Colour black</p>	250 €

		<p>Engine capacity: 2800 cc. Engine power: 93 Kw. Chassis number: 2G2AG51W5J9240866 Number of keys: 2</p> <p>Visible damage: right front wing, left rear door, left rear wing and general usage damage. (General user damage includes all damage that may be expected in view of the age and mileage.) You can always consult the photo report for a detailed overview.</p> <p>Car documents: Certificate of conformity: present. Application for registration: present.</p>	
	52	<p>BMW 5 Series</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 183452 km. 1st registration: 07/10/2011 Colour: Grey Engine capacity: 1995 cc. Engine power: 155 Kw. Emission class: Euro 5b CO² emissions: 143 g / km. Chassis number: WBAXB91090C591226 Number of keys: 1</p> <p>Option (s): air conditioning, alarm, on-board computer, central locking, cruise control, electric windows, leather interior, fog lamps, multifunction steering wheel, navigation, rear parking sensors, front parking sensors, radio / CD.</p> <p>Visible damage: rear bumper, INSIDE SEAT + dashboard and general usage damage. (General use damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p>	2.500 €

		<p>Car documents: Certificate of conformity: present. Registration certificate: available. Inspection certificate, valid until: 07/10/2020</p>	
	54	 <p>SKODA OCTAVIA Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 263069 km. 1st registration: 11/04/2012 Color: silver Engine capacity: 1598 cm³ Engine power: 77 kW Emission class: Euro 5 CO² emission: Chassis number: TMBHT21Z6C2170052 Number of keys: 1 Option (s): air conditioning, electric windows, fog lights, navigation, rear parking sensors, radio / CD. Damages: front left, front right, doors, rear bumper, rear right, rear left, gear lever, mirror controls. Visible Vehicle Damage: General usage damage. (General usage damage includes all damage that may be expected given the age and mileage.) For a detailed overview, please consult the photo report. Car documents: Certificate of conformity: present. Registration certificate: available. Identification report. Test certificate, valid until: 25/06/2021</p>	500 €
	69	 <p>PEUGEOT 508 Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 48151 km. 1st registration: 03/07/2019 Colour White Engine capacity: 1499 cc. Engine power: 96 Kw. Emission class: Euro 6 CO² emissions: unprecedented. Chassis number: VR3FBYHZRKY124689 Number of keys: 2 Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, leather interior, alloy wheels, fog lamps, multifunction steering wheel, navigation, open roof, rear parking sensors, front parking sensors, radio / CD, sports seats, seat heating.</p>	6.250 €

		<p>Extra info / options: GT-Line, rear view camera</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p>	
	70	<p>VOLKSWAGEN GOLF 1.6 TDI BREAK</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 315897 km. 1st registration: 10/04/2012 Colour: Grey Engine capacity: 1598 cc. Engine power: 77 Kw. Emission class: Euro 5a CO² emissions: 113 gr / km. Chassis number: WVWZZZ1KZCM662659 Number of keys: 1</p> <p>Option (s): air conditioning, on-board computer, central locking, cruise control, power windows, leather interior, alloy wheels, multifunction steering wheel, open roof, rear parking sensors, radio / CD.</p> <p>Visible damage: bonnet, rear right door, rear bumper, rear right bumper and general usage damage. (General user damage includes all damage that may be expected in view of the age and mileage.) You can always consult the photo report for a detailed overview.</p> <p>Car documents: Certificate of conformity: not present. Proof of registration: not present or incomplete.</p>	375 €

		The buyer receives a certificate of loss of vehicle documents.	
	70	<p>FORD Fiesta</p> <p>Category: Light commercial vehicle with a GVW less than or equal to 3.5 tonnes.</p> <p>Fuel: Diesel</p> <p>Transmission: Manual</p> <p>Mileage reading: 104965 km.</p> <p>1st registration: 26/03/2013</p> <p>Colour White</p> <p>Engine capacity: 1499 cc.</p> <p>Engine power: 55 Kw.</p> <p>Emission class: Euro 5a</p> <p>CO² emissions: 98 g / km.</p> <p>Chassis number: WF0RXXGAKRDM78636</p> <p>Number of keys: 3</p> <p>Option (s): air conditioning, central locking, electric windows, fog lights, multifunction steering wheel, rear parking sensors, radio / CD.</p> <p>Visible damage: left front bumper, front right rim, rear right rim, rear left bumper and general usage traces. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p> <p>Maintenance booklet, Identification report, Test certificate, valid until: 26/03/2021</p>	1.125 €
	71	<p>MAZDA 6</p> <p>Category: Passenger car.</p> <p>Fuel: Diesel</p> <p>Transmission: Manual</p>	375 €

		<p>Mileage reading: 245157 km. 1st registration: 22/06/2007 Colour: Grey Engine capacity: 1998 cc. Engine power: 89 Kw. Emission class: Euro 4 CO² emissions: 167 g / km. Chassis number: JMZGY19T671468980 Number of keys: 2</p> <p>Option (s): central locking, electric windows, multifunction steering wheel, radio / CD, towbar.</p> <p>Visible damage: front bumper, rear right wing and general usage damage. (General use damage includes all damage that can be expected given the age and mileage. For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p> <p>Carpass, Inspection certificate, valid until: 09/12/2018</p>	
	72	<p>VOLKSWAGEN Caddy</p> <p>Category: Light commercial vehicle with a GVW less than or equal to 3.5 tonnes. Fuel: Diesel Transmission: Manual Mileage reading: 91898 km. 1st registration: 07/07/2016 Colour black Engine capacity: 1968 cc. Engine power: 75 Kw. Emission class: Euro 6 CO² emissions: 120 gr / km. Chassis number: WV1ZZZ2KZHX007603 Number of keys: 2</p>	2.500 €

		<p>Option (s): air conditioning, on-board computer, central locking, electric windows, alloy wheels, fog lamps, navigation, rear parking sensors, radio / CD, towbar.</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p> <p>Identification report, Test certificate, valid until: 04/03/2021</p>	
	73	<p>SKODA Fabia</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 286827 km. 1st registration: 27/03/2012 Colour: Grey Engine capacity: 1199 cc. Engine power: 55 Kw. Emission class: Euro 5a CO² emissions: 99 g / km. Chassis number: TMBJK25J4C3153804 Number of keys: 1</p> <p>Option (s): central locking, power windows, fog lights, rear parking sensors, radio / CD.</p> <p>Visible damage: front bumper, right bumper, front left rim, hood, front right rim, rear right door, rear left rim, rear right rim, rear bumper, INSIDE SEAT and general usage traces. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p>	750 €

		<p>Car documents: Certificate of conformity: present. Registration certificate: available. Test certificate, valid until: 04/01/2021</p>	
	74	<p> FORD TransitConnect</p> <p>Category: Light commercial vehicle with a GVW less than or equal to 3.5 tonnes. Fuel: Diesel Transmission: Manual Mileage reading: 116903 km. 1st registration: 09/11/2012 Colour White Engine capacity: 1753 cc. Engine power: 66 Kw. Emission class: Euro 5a CO² emissions: 159 g / km. Chassis number: WF0TXXTTPTCB45567 Number of keys: 5</p> <p>Option (s): air conditioning, electric windows, fog lights, radio / CD.</p> <p>Visible vehicle damage: INSIDE SEAT and general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p> <p>Maintenance booklet, Identification report, Inspection certificate, valid until: 14/11/2020</p>	1.000 €

	75 Moped PEUGEOT T053A SPX Chassis no. : 3630008831 Mileage: 26277 Color blue Number of keys: 2 Certificate of conformity present. Registration certificate NOT present.	125 €
	76 HYUNDAI i30 Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 238431 km. 1st registration: 14/05/2012 Color yellow Engine capacity: 1582 cc. Engine power: 81 Kw. Emission class: Euro 5a CO ² emissions: 97 g / km. Chassis number: TMAD351UADJ016478 Number of keys: 1 Option (s): on-board computer, electric windows, fog lamps, radio / CD. Visible damage: front bumper, front right bumper, front right wing, right wing mirror, front left door, rear left door, rear right door, rear left bumper, rear right wing and general usage traces. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report. Car documents: Certificate of conformity: present. Registration certificate: available. Carpass, Test certificate, valid until: 26/09/2020	625 €

	77	<p>Volkswagen Golf</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 250751 km. 1st registration: 04/04/2016 Colour: Grey Engine capacity: 1598 cc. Engine power: 81 Kw. Emission class: Euro 6 CO² emissions: 99 g / km. Chassis number: WVWZZZAUZGP098844 Number of keys: 2</p> <p>Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, alloy wheels, fog lamps, multifunction steering wheel, navigation, rear parking sensors, front parking sensors, radio / CD.</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available. Test certificate, valid until: 04/04 // 2021</p>	1.000 €
	80	<p>AUDI A4</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 165272 km. 1st registration: 28/08/2008 Colour black Engine capacity: 1968 cc. Motor power: 100 Kw. Emission class: Euro 4 CO² emissions: 172 gr / km.</p>	1.500 €

		<p>Chassis number: WAUZZZ8H08K005787 Number of keys: 1</p> <p>Option (s): central locking, cruise control, electric windows, leather interior, fog lamps, rear parking sensors, radio / CD, sports seats, seat heating.</p> <p>Visible damage: front left bumper, front right bumper, hood, windshield, boot lid and general usage traces. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: not present. Registration certificate: available.</p> <p>The buyer receives a certificate of loss of car documents. Inspection certificate, valid until: 14/03/2016</p>	
	81	<p>SEAT Alhambra</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 142285 km. 1st registration: 08/11/2017 Colour black Engine capacity: 1968 cc. Engine power: 110 Kw. Emission class: Euro 6 CO² emissions: 137 gr / km. Chassis number: VSSZZZ7NZHV719591 Number of keys: 1</p> <p>Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, leather interior, fog lamps, multifunction steering wheel, navigation, front parking sensors, radio / CD. Extra info / options: rear view camera</p> <p>Visible damage: front right bumper, rear right door, rear</p>	4.375 €

		<p>left bumper, rear bumper, rear left wing, rear right wing and general usage traces. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available. Inspection certificate, valid until: 14/11/2020</p>	
	82	<p> FORD TransitConnect</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 269453 km. 1st registration: 05/12/2017 Colour: Grey Engine capacity: 1995 cc. Engine power: 125 Kw. Emission class: Euro 6 CO² emissions: 163 g / km. Chassis number: WF01XXTTG1GC74747 Number of keys: 2</p> <p>Option (s): on-board computer, central locking, cruise control, electric windows, fog lights, multifunction steering wheel, navigation, rear parking sensors, front parking sensors, radio / CD.</p> <p>Visible vehicle damage: INSIDE SEAT and general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p>	1.875 €

		Test certificate, valid until: 11/06/2020	
	83	<p>PORSCHE Cayenne</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 239612 km. 1st registration: 02/01/2015 Colour black Engine capacity: 4134 cc. Engine power: 283 Kw. Emission class: Euro 5b CO² emissions: 209 g / km. Chassis number: WP1ZZZ92ZFLA66708 Number of keys: 2</p> <p>Option (s): air conditioning, alarm, on-board computer, central locking, cruise control, electric windows, leather interior, fog lights, multifunction steering wheel, navigation, open roof, rear parking sensors, front parking sensors, radio / CD, sports seats, seat heating. Extra info / options: Sport, rear view camera</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: Incomplete.</p> <p>The buyer receives a certificate of loss of car documents.</p> <p>Test certificate, valid until: 02/01/2021</p>	6.875 €
	84	<p>PORSCHE Cayenne</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Automatic</p>	7.500 €

		<p>Mileage reading: 93889 km. 1st registration: unknown. Colour black Engine capacity: unprecedented. Engine power: unprecedented. Emission class: unprecedented. CO² emissions: unprecedented. Chassis number: WP1ZZZ92ZJLA65323 Number of keys: 2</p> <p>Option (s): air conditioning, alarm, on-board computer, central locking, cruise control, electric windows, leather interior, fog lights, multifunction steering wheel, navigation, open roof, rear parking sensors, front parking sensors, radio / CD, sports seats, seat heating. Extra info / options: rear view camera, sports, seat cooling</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: incomplete.</p> <p>Test certificate: Valid until 10/11/2021</p> <p>The buyer receives a certificate of loss of car documents.</p>	
	85	 <p>Motorcycle DERBI TERRA 125 Chassis no.: VTHTS1A1A8H388165 Colour black Fuel gasoline Number of keys: 1 Engine capacity: 124 cm³ Engine power: 11 kW Environmental class: EURO 3</p> <p>Registration certificate available. Certificate of conformity present.</p>	250 €

	86	CITROËN C4 Cactus Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 140138 km. 1st registration: 28/06/2016 Color red Engine capacity: 156 cc. Engine power: 73 Kw. Emission class: Euro 6 CO ² emissions: 89 g / km. Chassis number: VF70BBHYHGE543742 Number of keys: 1 Option (s): air conditioning, on-board computer, cruise control, electric windows, fog lights, multifunction steering wheel, radio / CD. Visible vehicle damage: front left bumper, front right bumper, windshield, front left door, front right door, rear left door, rear right door, rear left rim, rear right rim, rear left bumper, rear bumper, rear right bumper, left headlight, right headlight, left rear wing, right rear wing, left rear light, right rear light and general usage traces. (General use damage includes all damage that can be expected given the age and mileage. For a detailed overview you can always consult the photo report. Car documents: Certificate of conformity: present. Registration certificate: available.	1.250 €
	87	CITROËN C4 Cactus Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 147602 km. 1st registration: 28/06/2016 Color red Engine capacity: 1560 cc.	1.250 €

		<p>Engine power: 73 Kw. Emission class: Euro 6 CO² emissions: 89 g / km. Chassis number: VF70BBHYHGE543284 Number of keys: 1</p> <p>Option (s): air conditioning, cruise control, electric windows, fog lights, multifunction steering wheel, radio / CD.</p> <p>Visible vehicle damage: front left bumper, front right bumper, front left rim, left rear light, MESSAGES ENGINE + BRAKES! and general usage damage. (General use damage includes all damage that can be expected given the age and mileage. For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available. Inspection certificate, valid until: 05/07/2020</p>	
	88	 <p>CITROËN C4 Cactus</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 131071 km. 1st registration: 08/07/2016 Color red Engine capacity: 1560 cc. Engine power: 73 Kw. Emission class: Euro 6 CO² emissions: 89 g / km. Chassis number: VF70BBHYHGE543285 Number of keys: 2</p> <p>Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, fog lights, multifunction steering wheel, radio / CD.</p>	2.000 €

		<p>Visible damage: front right rim, left exterior mirror, right rear door, right rear rim, left rear light and general usage traces. (General use damage includes all damage that can be expected given the age and mileage. For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available. Test certificate, valid until: 13/07/2020</p>	
	89	<p>CITROËN C4 Cactus</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: UNKNOWN km. 1st registration: 08/07/2016 Color red Engine capacity: 1560 cc. Engine power: 73 Kw. Emission class: Euro 6 CO² emissions: 89 g / km. Chassis number: VF70BBHYHGE543286 Number of keys: 3</p> <p>Option (s): air conditioning, on-board computer, cruise control, electric windows, fog lights, multifunction steering wheel, radio / CD.</p> <p>Visible vehicle damage: left front door, roof, right front door, left rear door, right rear door, right rear wing, DO NOT START !! and general usage damage. (General use damage includes all damage that can be expected given the age and mileage. For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present.</p>	1.000 €

		Registration certificate: available.	
	90	<p>CITROËN C4 Cactus</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 120947 km. 1st registration: 25/10/2016 Color red Engine capacity: 1560 cc. Engine power: 73 Kw. Emission class: Euro 6 CO² emissions: 89 g / km. Chassis number: VF70BBHYHGE565794 Number of keys: 1</p> <p>Option (s): air conditioning, cruise control, electric windows, fog lights, multifunction steering wheel, radio / CD. Extra info / options: ACCIDENT - AIRBAGS OPEN!</p> <p>Visible damage: front bumper, front left bumper, front right bumper, front left wing, bonnet, front right wing, front right rim, windshield, outside right mirror, front left door, front right door, rear left door, rear left rim, left headlight, right headlight, front right window, left rear light and general usage damage. (General use damage includes all damage that can be expected given the age and mileage. For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p>	125 €
	91	<p>IVECO EUROTRAKKER</p> <p>Category: Truck or tractor with a GVW of more than 12 tonnes. Fuel: Diesel Transmission: Manual</p>	750 €

		<p>Mileage reading: 566706 km. 1st registration: 25/07/2005 Colour: Grey Engine capacity: 12900 cc. Engine power: 324 Kw. Emission class: Euro 3 CO² emissions: unprecedented. Chassis number: WYME3TST20C150164 Number of keys: 2</p> <p>Option (s): radio / CD. Extra info / options: LOAD BODY GOES UP</p> <p>Visible vehicle damage: PISTON TO REPLACE ON TAP (OIL LEAKING) and general usage damage. (General use damage includes all damage that can be expected given the age and mileage. For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p> <p>Identification report, Test certificate, valid until: 26/09/2020</p>	
	191	 <p>PORSCHE 911 carrera 4</p> <p>Category: unknown. Fuel gasoline Transmission: Automatic Odometer reading: 178 617 km. 1st registration: 23/10/1998 Color blue Engine capacity: 3387 cc. Engine power: 221 Kw. Emission class: unknown. CO² emissions: unprecedented. Chassis number: WP0ZZZ99ZXS601668 Number of keys: 1</p> <p>Option (s): air conditioning, alarm, central locking, cruise control, electric windows, leather interior, alloy wheels,</p>	5.250 €

		<p>multifunction steering wheel, radio / CD.</p> <p>Visible damage: right rear door and general use damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Board documents: Certificate of conformity: present. Certificate of registration: present. Test certificate, valid until: 12/08/2018</p>	
	210	<p> Mercedes-Benz E 200 D.</p> <p>condition: Used Make: Mercedes-Benz Model: E 200 D Body style: Saloon Category: M1: carriage of passenger designed and constructed vehicles with a maximum of eight seats, excluding driver Fuel: Diesel Transmission: Automatic Odometer reading: km Odometer reading: 191127 First registration dd / mm / yyyy: 23/10/2017</p> <p>Exterior color: Black Cylinder capacity cc: 1950 Motor power kW: 110 Emission class: Euro 6c CO2 emission gr / km: 102 Chassis number: WDD2130131A339034 Number of keys: 2 Interior color: Black Interior material: Full leather</p> <p>Options: Air conditioning: Yes Board computer: Yes Multi-function handlebar: Yes Central locking: Yes</p>	6.165 €

		<p>Electric seat adjustment: Yes Seat heating: Yes Navigation: Yes Radio: Yes Parking sensors: Yes Reversing camera: Yes Cruise control: Yes Electric windows: Yes Electric folding mirrors: Yes Alloy wheels: Yes</p> <p>Board documents: Certificate of registration: Present Certificate of conformity: Present Test certificate: Present Test certificate valid until dd / mm / yyyy: 25/10/2020</p> <p>Vehicle damage: No, we have not established general use damage (exceptional damage that can be expected given the age and mileage)</p>	
	212	 <p>CITROËN Berlingo</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Odometer reading: 221,804 km. 1st registration: 14/02/2008 Color red Engine capacity: 1560 cc. Engine power: 55 Kw. Emission class: Euro 4 CO² emission: 140 gr / km. Chassis number: VF7GJ9HWC93507234 Number of keys: 1</p> <p>Option (s): electric windows, radio / CD, tow bar.</p> <p>Visible damage: front bumper, front bumper, left, front bumper, right, left front wing, right front wing, windshield, right door mirror, right front door, right rear door, trunk lid, left rear bumper, right rear bumper, left rear light, right rear light, Vehicle highly braking bad and general usage damage.</p>	250 €

		<p>(General usage damage includes all damage that can be expected given the age and mileage.)</p> <p>For a detailed overview you can always consult the photo report.</p> <p>Board documents:</p> <p>Certificate of conformity: present.</p> <p>Certificate of registration: not present or incomplete.</p> <p>The buyer must request the missing papers himself.</p> <p>Neither Moyersoen or his client, nor the guardianship will vouch for this.</p> <p>Test certificate, valid until: 11/10/2019</p>	
	350	<p>VOLKSWAGEN Transporter</p> <p>Category: Light commercial vehicle with a GVW less than or equal to 3.5 tons.</p> <p>Fuel: Diesel</p> <p>Transmission: Manual</p> <p>Mileage reading: 163257 km.</p> <p>1st registration: 25/06/2013</p> <p>Colour black</p> <p>Engine capacity: 1968 cc.</p> <p>Engine power: 75 Kw.</p> <p>Emission class: Euro 5a</p> <p>CO² emissions: unprecedented.</p> <p>Chassis number: WV1ZZZ7HZDX015503</p> <p>Number of keys: 1</p> <p>Option (s): air conditioning, on-board computer, central locking, electric windows, fog lamps, navigation, rear parking sensors, radio / CD.</p> <p>Visible damage: windshield, left wing mirror, left front door, right front door, left rear door, right rear door, trunk lid and general usage traces.</p> <p>(General usage damage includes all damage that can be expected given the age and mileage.)</p> <p>For a detailed overview you can always consult the photo report.</p> <p>Car documents:</p>	2.500 €

		<p>Certificate of conformity: present. Certificate of registration: present.</p> <p>Carpass, Identification report, Test certificate, valid until: 28/10/2020</p>	
	391	<p> MAZDA 3</p> <p>Category: Passenger car. Fuel gasoline Transmission: Manual Mileage reading: 151744 km. 1st registration: 25/02/2004 Color blue Engine capacity: 1349 cc. Engine power: 62 Kw. Emission class: Euro 4 CO² emissions: 169 gr / km. Chassis number: JMZBK14J241134763 Number of keys: 1</p> <p>Option (s): electric windows, fog lights, multifunction steering wheel, radio / CD.</p> <p>Visible damage: front right bumper, front left wing, front right wing, front right rim, front left door, front right door, rear right door, boot lid, rear left bumper, rear bumper, rear left wing and general usage traces. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available. Test certificate, valid until: 0</p>	625 €

	395	<p>RENAULT Master</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: unknown km. 1st registration: 01/09/2008 Colour White Engine capacity: unknown cc. Engine power: unknown Kw. Emission class: unprecedented. CO² emissions: unprecedented. Chassis number: VF1NDD21639064974 Number of keys: 1</p> <p>Option (s): electric windows, fog lights, radio / CD. Extra info / options: MINIBUS: 15 + 1 SEATS + TACHOGRAPH + ALCOHOL LOCK</p> <p>Visible damage: rear right door, DRIVER DOOR LOCK PIECE and general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: not present. Certificate of registration: present (French) customs document E705</p> <p>The buyer must request a Certificate of Conformity himself</p>	1.250 €
	417	<p>SSANGYONG Actyon</p> <p>Category: Light commercial vehicle with a GVW less than or equal to 3.5 tons. Fuel: Diesel Transmission: Manual Mileage reading: 35009 km. 1st registration: 15/11/2016 Colour black Engine capacity: 2157 cc.</p>	5.250 €

		<p>Engine power: 130 Kw. Emission class: Euro 6 CO₂ emissions: 186 g / km. Chassis number: KPACA1EESH P285342 Number of keys: 2</p> <p>Option (s): air conditioning, central locking, cruise control, electric windows, multifunction steering wheel, rear parking sensors, radio / CD, tow bar, seat heating.</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: not present. Registration certificate: available.</p> <p>The buyer receives a certificate of loss of vehicle documents.</p> <p>Carpass, Identification report, Test certificate, valid until: 30/04/2019</p>	
	434	 <p>FIAT Doblo</p> <p>Category: Passenger car. Fuel: CNG Transmission: Manual Mileage reading: 121966 km. 1st registration: 23/10/2014 Colour: Grey Engine capacity: 1368 cc. Engine power: 88 Kw. Emission class: Euro 6 CO₂ emissions: 134 g / km. Chassis number: ZFA26300006189437 Number of keys: 2</p> <p>Option (s): air conditioning, electric windows, radio / CD.</p>	2.500 €

		<p>Visible damage: front left bumper, front left wing, right wing mirror, left front door, left rear rim, rear bumper and general usage traces. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available. Inspection certificate, valid until: 23/10/2020</p>	
	2052	<p>FORD TRANSIT</p> <p>Category: Light commercial vehicle with an MTM smaller or equal to 3.5 tons. Fuel: Diesel Transmission: Manual Mileage reading: 214308 km. 1st registration: 24/03/2005 Color: silver Engine capacity: unknown. Engine power: unprecedented. Emission class: unknown. CO² emissions: unprecedented. Chassis number: WF0PXXBDFP5M30623 Number of keys: 1</p> <p>Option (s): no standard options available. Extra info / options: Dutch registration certificate present. The buyer himself will take the necessary steps to obtain the correct documents. Neither Moyersoen nor his client will assist the buyer in this.</p> <p>Visible damage: Suspension front right severely damaged (spring broken). Lots of corrosion all around, including poorly recovered. and general usage damage. (General user damage includes all damage that may be expected given the age and mileage.) You can always consult the photo report for a detailed overview.</p>	150 €

		<p>Car documents: Certificate of conformity: not present. Proof of registration: not present or incomplete.</p> <p>The buyer must request the missing papers himself. Neither Moyersoen or his client, nor the guardianship will guarantee this.</p>	
	2158	<p>Citroën Jumper van</p> <p>condition: Used Brand: Citroen Model: Jumper Category: N1: max mass <3.5t. Fuel: Diesel Transmission: Manual Odometer reading: km Odometer reading: 260555 First registration dd / mm / yyyy: 23/05/2007</p> <p>Exterior color: White Cylinder capacity cc: 2198 Motor power kW: 88 Emission class: Euro 4 Chassis number: VF7YDBMFB11202776 Number of keys: 1 Interior color: Gray Interior material: Fabric</p> <p>Options: Air conditioning: Yes Board computer: Yes Central locking: Yes Radio: Yes</p> <p>Board documents: Certificate of registration: Present Certificate of conformity: Present CARPASS: Not present Identification report: Not available Test certificate: Not present Maintenance book: Not present</p> <p>Vehicle damage: Yes, for a detailed overview of the visible</p>	500 €

		<p>damage, you can always consult the photo report.</p> <p>Vehicle damage description: Severe soot damage all around, engine problem: vehicle produces excessive smoke, difficult to start,</p>	
	2198	<p>IVECO CARGO</p> <p>Category: Truck or tractor with a GVW of more than 3.5 tonnes and less than or equal to 12 tonnes.</p> <p>Fuel: Diesel</p> <p>Transmission: Automatic</p> <p>Mileage reading: 86685 km.</p> <p>1st registration: 29/05/2013</p> <p>Colour black</p> <p>Engine capacity: 3920 cc.</p> <p>Engine power: 134 Kw.</p> <p>Emission class: unprecedented.</p> <p>CO² emissions: unprecedented.</p> <p>Chassis number: ZCFA1ED1402609549</p> <p>Number of keys: 1 + 1</p> <p>Option (s): cruise control, power windows, fog lights.</p> <p>Visible vehicle damage: left rear door and general usage damage. (General use damage includes all damage that can be expected given the age and mileage. For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available. Test certificate, valid until: 31/05/2020</p>	1.000 €
	2199	<p>IVECO Daily</p> <p>Category: Light commercial vehicle with a GVW less than or equal to 3.5 tonnes.</p> <p>Fuel: Diesel</p> <p>Transmission: Manual</p> <p>Mileage reading: 122507 km.</p>	2.500 €

	<p>1st registration: 19/08/2013 Colour White Engine capacity: 2998 cc. Engine power: 125 Kw. Emission class: Euro 5a CO² emissions: 222 g / km. Chassis number: ZCFC35C200D489329 Number of keys: 1</p> <p>Option (s): cruise control, electric windows, radio / CD, tow bar.</p> <p>Visible vehicle damage: general usage damage. (General use damage includes all damage that can be expected given the age and mileage. For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available. Inspection certificate, valid until: 21/08/2020</p>	
--	---	--

