



AUCTIM
POWERED BY MOYERSOEN

CATALOG

Cars and commercial vehicles



DESCRIPTION

Passenger cars and commercial vehicles from various bankruptcies, seizures and breaches of contract and others

START

23 february 2021 to 10:00

END DATE

2 march 2021 from 19:00

VIEWING

- Wednesday February 24 2021 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452.153.622

DELIVERY

- Wednesday March 10 2021 from 09:00 until 12:00
BE-2630 Aartselaar, Helststraat 47

Online bidding only!

Catalog created on 2 march 2021 to 05:00

	Lot	Description	Start price
	24	<p>KEMPF SKM SM035 dumper truck</p> <p>Year of construction: 2012 Chassis no .: WKY3S2135CM026266 1st registration: 24/07/2012 Colour: Grey Number of axles: 3 GVW: 35000 kg Payload: 27 750 kg Dimensions: 10450x2550x4000 mm</p> <p>Registration certificate: available Identification report available. Inspection certificate valid until: 18/12/2020.</p> <p>The buyer will receive a certificate of loss of car documents.</p>	4.500 €
	25	<p>HARCON LB1400 / 50 leveler bucket</p> <p>Year of construction: 2019 Serial no .: 30301018 Color yellow Dimensions: transport width 1485 mm, blade height 500 mm, blade width 1400 mm, hydraulic side doors 12 mm thick, adjustable from 1400 to 2200 mm Hydraulic double slope frame. Hydraulic block 4 sections incl. Hoses. Including DTech D4000 control, slightly damaged.</p>	4.500 €
	88	<p>MERCEDES B 180</p> <p>Category: Passenger car. Fuel gasoline Transmission: Automatic Mileage reading: 39036 km. 1st registration: 29/03/2018 Colour: Grey Engine capacity: 1595 cc. Engine power: 90 Kw. Emission class: Euro 6</p>	2.550 €

		<p>CO² emissions: 127 g / km. Chassis number: WDD2462421J481660 Number of keys: 2</p> <p>Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, fog lights, multifunction steering wheel, navigation, rear parking sensors, front parking sensors, radio / CD, seat heating. Extra info / options: rear view camera, electric mirrors</p> <p>Visible damage: rear left bumper, front right bumper and general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p> <p>Carpass, Test certificate, valid until: 29/03/2022</p>	
	89	<p>AUDI S5 Sportback</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Automatic Mileage reading: 19853 km. 1st registration: 30/08/2019 Colour: Grey Engine capacity: 3000 cc. Engine power: 255 Kw. Emission class: Euro 6 CO² emissions: unprecedented. Chassis number: WAUZZZF56KA061772 Number of keys: 2</p> <p>Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, leather interior, alloy wheels, fog lamps, multifunction steering wheel, navigation, open roof, rear parking sensors, front parking sensors, radio / CD, sports seats, seat heating.</p>	7.500 €



		<p>Extra info / options: S-LINE, rear view + 360 ° camera, electric seats with memory function, electric mirrors, carplay</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p> <p>Carpas, Test certificate, valid until: 30/08/2023</p>	
	90	<p>TOYOTA Aygo 5 d. 1.0 VVT-i 5MT x-style LHD</p> <p>Category: Passenger car. Fuel gasoline Transmission: Manual Mileage reading: 69643 km. 1st registration: 06/06/2019 Color red Engine capacity: 998 cc. Engine power: 53 Kw. Emission class: Euro 6 CO² emissions: 114 gr / km. Chassis number: JTDKGNEC40N375087 Number of keys: 1</p> <p>Option (s): air conditioning, alarm, on-board computer, central locking, cruise control, electric windows, multifunction steering wheel, navigation, radio / CD. Extra info / options: rear view camera</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents:</p>	900 €

		<p>Certificate of conformity: present. Registration certificate: available.</p> <p>Maintenance book.</p>	
	92	<p>VOLKSWAGEN Golf Variant 1.6 TLBMT</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 203766 km. 1st registration: 19/12/2013 Colour black Engine capacity: 1598 cc. Engine power: 77 Kw. Emission class: Euro 5a CO² emissions: 102 g / km. Chassis number: WVWZZZAUZEP546506 Number of keys: 1</p> <p>Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, fog lights, multifunction steering wheel, navigation, radio / CD.</p> <p>Visible damage: front left bumper, front right bumper and general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: missing or incomplete.</p> <p>The buyer receives a certificate of loss of car documents. Test certificate, valid until: 19/12/2020</p>	975 €
	93	<p>VOLKSWAGEN Golf Variant 1.6 TLBMT</p> <p>Category: Passenger car. Fuel: Diesel</p>	900 €

		<p>Transmission: Manual Mileage reading: 278235 km. 1st registration: 28/01/2015 Colour black Engine capacity: 1598 cc. Engine power: 77 Kw. Emission class: Euro 5b CO² emissions: 102 g / km. Chassis number: WVWZZZAUZFP590124 Number of keys: 1</p> <p>Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, fog lights, multifunction steering wheel, navigation, rear parking sensors, front parking sensors, radio / CD.</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: missing or incomplete.</p> <p>The buyer receives a certificate of loss of car documents. Test certificate, valid until: 28/01/2021</p>	
	94	<p>VOLVO XC90 Momentum 7-seater D4 Geartronic</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 57256 km. 1st registration: 20/08/2018 Colour: Grey Engine capacity: 1969 cc. Engine power: 140 Kw. Emission class: Euro 6 CO² emissions: unprecedented. Chassis number: YV1LFA8BDJ1390067 Number of keys: 2</p>	5.250 €

		<p>Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, leather interior, fog lamps, multifunction steering wheel, navigation, rear parking sensors, front parking sensors, radio / CD. Extra info / options: electric seats with memory function</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available. Test certificate, valid until: 09/10/2021</p>	
	142	<p>VOLVO V60 D2</p> <p>Category: Passenger car. Fuel: Diesel Transmission: Manual Mileage reading: 188614 km. 1st registration: 04/02/2016 Colour black Engine capacity: 1969 cc. Engine power: 88 Kw. Emission class: Euro 6 CO² emissions: 101 g / km. Chassis number: YV1FW74C161317225 Number of keys: 2</p> <p>Option (s): air conditioning, central locking, cruise control, electric windows, leather interior, fog lights, multifunction steering wheel, navigation, rear parking sensors, front parking sensors, radio / CD, seat heating.</p> <p>Visible vehicle damage: bonnet, boot lid, rear left bumper and general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo</p>	1.200 €



		<p>report.</p> <p>Car documents: Certificate of conformity: not present. Registration certificate: missing or incomplete.</p> <p>The buyer will receive a certificate of loss of car documents.</p>	
	1012	<p>OPEL Movano L2H2</p> <p>Category: Light commercial vehicle with a GVW less than or equal to 3.5 tonnes. Fuel: Diesel Transmission: Manual Mileage reading: 84199 km. 1st registration: 31/01/2018 Colour black Engine capacity: 2299 cc. Engine power: 107 Kw. Emission class: Euro 6 CO² emissions: 183 gr / km. Chassis number: W0VMRS606HB139484 Number of keys: 1</p> <p>Option (s): air conditioning, central locking, cruise control, electric windows, fog lights, multifunction steering wheel, navigation, rear parking sensors, radio / CD, towbar. Extra info / options: rear view camera</p> <p>Visible vehicle damage: left rear flank and general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: missing or incomplete.</p> <p>The buyer receives a certificate of loss of car documents.</p> <p>Identification report,</p>	2.100 €

		Test certificate, valid until: 01/02/2021	
	1013	<p>MERCEDES Sprinter 314 CDI GB L2 RWD</p> <p>Category: Light commercial vehicle with a GVW less than or equal to 3.5 tons. Fuel: Diesel Transmission: Manual Mileage reading: 5383 km. 1st registration: 19/07/2019 Colour White Engine capacity: 2143 cc. Engine power: 105 Kw. Emission class: Euro 6 CO² emissions: unprecedented. Chassis number: WDB9076331P047798 Number of keys: 1</p> <p>Option (s): air conditioning, central locking, cruise control, electric windows, fog lights, multifunction steering wheel, radio / CD. Extra info / options: refrigeration cell</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p>	4.050 €
	1014	<p>OPEL Vivaro L2H1</p> <p>Category: Light commercial vehicle with a GVW less than or equal to 3.5 tons. Fuel: Diesel Transmission: Manual Mileage reading: 9593 km. 1st registration: 05/02/2020 Colour black Engine capacity: 1997 cc.</p>	3.000 €

		<p>Engine power: 110 Kw. Emission class: Euro 6 CO² emissions: unprecedented. Chassis number: VXEVFAHXKLZ013971 Number of keys: 2</p> <p>Option (s): air conditioning, on-board computer, central locking, cruise control, electric windows, fog lights, multifunction steering wheel, navigation, rear parking sensors, front parking sensors, radio / CD, towbar. Extra info / options: DAB + radio, rear view camera</p> <p>Visible vehicle damage: general usage damage. (General usage damage includes all damage that can be expected given the age and mileage.) For a detailed overview you can always consult the photo report.</p> <p>Car documents: Certificate of conformity: present. Registration certificate: available.</p> <p>Maintenance booklet, Identification report, Test certificate, valid until: 27/02/2021</p>	
	1043	<p>SCANIA R580 N320 tractor unit</p> <p>Chassis no.: YS2R4X20009214246 1st registration: 10/10/2016 Vehicle class: N3 Number of axles: 2 Mileage: 476617 km Colour black Number of keys: 1 Transmission: Automatic Fuel: Diesel</p> <p>Engine capacity: 16353 cm³ Engine power: 427 kW Environmental class: Euro 6 GVW: 18000 kg</p> <p>Registration certificate: available Inspection certificate present: valid until 18/04/2021</p>	7.500 €



		Identification report available. The buyer will receive a certificate of loss of car documents.	
--	--	--	--

